

IN DILUTION ONE (1) PART SUPERWASH TO THREE (3) PARTS TAP WATER

RECOMMENDED FOR:

Floor & Wall Cleaner

Terrazzo

Tile

Marble

Wood

Concrete

Stainless Steel

Vinyls

Fiberglass

Carpets

Whitewall Tires

Engine Degreasing

Machinery

FOR REMOVAL OF:

Oils & Grease

Wax & Carbon

Blood & Tallow

Soap Scum

Waterline Scum

Magic Marker

Printers Ink

Food Stains

Sugar & Syrups

DIRECTIONS:

1. Spray on, full concentrate.
(Do not wet area to be cleaned, except with SuperWash solution.)
2. Let stand one to three minutes.
3. Agitate or brush heavily soiled areas.
4. Rinse thoroughly as you brush.

NOTE: This is a concentrated alkaline cleaner. When used for cleaning some aluminums and painted surfaces, dilute with water or rinse thoroughly with water immediately.

S.W.I. INTERNATIONAL



487 Division Street
Boonton, NJ 07005
(973) 334-2525